

## G203V TROUBLESHOOTING: MOTOR WON'T MOVE

NOTE: "CODExx" IS THE ERROR CODE DESCRIBING THE PROBLEM WITH G203V DRIVES BEING RETURNED FOR SERVICE. INCLUDE THE CODE WITH THE RETURNED DRIVE.

